

Incident Notification

Incident Date: December 14, 2020

Title: Dangerous Occurrence

Description: While one of the secondary leach tanks at the McClean Lake operation was bypassed for maintenance, the air system feeding to that tank was also mistakenly bypassed, leading to a potential unsafe condition.

Resolution: The air system was returned to service a couple of hours later and worked as expected to respond to elevated hydrogen levels in the tank.

Effect: The event has been reported to federal and provincial regulators and is being investigated. There were no effects to the environment or the health and safety of workers.

